
Installation Manual





Contents Overview



(×6)

 $(\times 4)$




Intermediate T Element 3-15-2224



Self Adhesive Rubber Button 3-15-2240

(8x)



50mm × 50mm Clear **Anodized Square Tube 10'** 0-15-2231





5mm × 17mm **Connector Screws** 3-15-2236



50mm End Cap with M10 Thread 3-15-2225





6mm × 16mm **Cap Head Screw** 3-15-2234-K




3-15-2237


 $(\times 4)$



Stainless Steel Adjustable Leg for 50 × 50 Tube, 10mm Thread 3-15-2241



Corner and Cap for Vertical 50 × 50 Tube 3-15-2242-K




3-15-2234


Square Bottom 3-15-2242 Plate Covers 3-15-0100



Corner Element for Horizontal 50 × 50 Tube 3-15-2243-K



Overview



Installation

Required Tools






Metric Allen Wrenches


Rubber Mallet

1 Attach Corner Blocks to Table Legs

*Repeat this step for all 4 legs

a







Installation

2 Attach T Intersection at Lower Horizontal Members

a




b






Installation

3 Attach Square Tube Profiles to Table Legs




b Attach profile to leg with screw (3-15-0796) on underside.






Installation

4 Attach Crossbar




5 Attach Corner Covers




Installation

6 Attach Feet to Legs



7 Attach Stick-On Buttons to Frame where Panel will Sit



Installation

8 Place Table Top

